



SPECTRA

2000 HOUR SERVICE METER RESET

1. Hold Down These Keys Simultaneously:



2. Enter Code:



3. Confirm Code:



4. Scroll To Service Time:



5. Press "Up Limit":



6. To Reset, Press "Down Limit":



7. To Validate, Press "Up Limit":



8. To Return To Operation Mode,
Press "Down limit":



The reset of the 2000 Hour Meter is complete.